STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155237	A. BUILDING 02 B. WING _____	02/12/2013

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
BETHANY VILLAGE NURSING HOME	3518 S SHELBY ST INDIANAPOLIS, IN 46227

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 000	INITIAL COMMENTS A Life Safety Code and Environmental Preoccupancy Survey for the addition of a newly constructed therapy wing was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 02/12/13 Facility Number: 000142 Provider Number: 155237 AIM Number: 100266940 Surveyor: Mark Caraher, Life Safety Code Specialist At this Life Safety Code and Environmental Preoccupancy survey, Bethany Village Nursing Home was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety From Fire and the 2000 Edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 18, New Health Care Occupancies and 410 IAC 16.2-3.1-19, Environment and Physical Standards of the Indiana Health Facilities Rules for Comprehensive care facilities for the addition of a newly constructed therapy wing. This one story facility was determined to be of Type V (000) construction and fully sprinklered. The facility has a fire alarm system with hard wired smoke detection in the corridors, in all areas open to the corridor and in all resident sleeping rooms. The facility has a capacity of 100 and had a census of 89 at the time of this visit.	K 000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE | TITLE | (X6) DATE

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	155237	A. BUILDING 02 B. WING _____	02/12/2013

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
BETHANY VILLAGE NURSING HOME	3518 S SHELBY ST INDIANAPOLIS, IN 46227

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 000	Continued From page 1 All areas where residents have customary access were sprinklered. The facility has an unsprinklered wood shed providing facility storage. Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 02/12/13.	K 000		